



Your Inspection Report

118 Torbrick Road
Toronto, ON M4J 4Z5

PREPARED FOR:

TREVOR BOND
LISTING AGENT

INSPECTION DATE:

Friday, September 8, 2023

PREPARED BY:

Scott Aitken

Aitken Home Inspections
49 Riverdale Ave
TORONTO, ON M4K 1C2

4164074663
scottaitken@live.ca

September 8, 2023

Dear Trevor Bond and Listing Agent,

RE: Report No. 3863
118 Torbrick Road
Toronto, ON
M4J 4Z5

Thanks very much for choosing us to perform your home inspection. The inspection itself and the attached report comply with the requirements of the Standards of Practice of our national Association. This document defines the scope of a home inspection.

Clients sometimes assume that a home inspection will include many things that are beyond the scope. We encourage you to read the Standards of Practice so that you clearly understand what things are included in the home inspection and report.

The report has been prepared for the exclusive use of our client. No use by third parties is intended. We will not be responsible to any parties for the contents of the report, other than the party named herein .

The report is effectively a snapshot of the house, recording the conditions on a given date and time. Home inspectors cannot predict future behavior, and as such, we cannot be responsible for things that occur after the inspection. If conditions change, we are available to revisit the property and update our report.

The report itself is copyrighted, and may not be used in whole or in part without our express written permission.

Again, thanks very much for choosing us to perform your home inspection.

Sincerely,

Scott Aitken
on behalf of
Aitken Home Inspections

Aitken Home Inspections
49 Riverdale Ave
TORONTO, ON M4K 1C2
4164074663

scottaitken@live.ca

AGREEMENT

Report No. 3863

118 Torbrick Road, Toronto, ON September 8, 2023

PARTIES TO THE AGREEMENT

Company

Aitken Home Inspections
49 Riverdale Ave
TORONTO, ON M4K 1C2

Client

Trevor Bond

Client

Listing Agent

This is an agreement between Trevor Bond, Listing Agent and Aitken Home Inspections.

**THIS CONTRACT LIMITS THE LIABILITY OF THE HOME INSPECTION COMPANY.
PLEASE READ CAREFULLY BEFORE SIGNING.**

In addition to the limitations in the Standards of Practice, the Inspection of this property is subject to the Limitations and Conditions set out in this Agreement. The Inspection is performed in accordance with the Standards of Practice of our national association.

LIMITATIONS AND CONDITIONS OF THE HOME INSPECTION

There are limitations to the scope of this Inspection. It provides a general overview of the more obvious repairs that may be needed. It is not intended to be an exhaustive list. The ultimate decision of what to repair or replace is yours. One homeowner may decide that certain conditions require repair or replacement, while another will not.

1) THE INSPECTION IS NOT TECHNICALLY EXHAUSTIVE.

The Home Inspection provides you with a basic overview of the condition of the property. Because your Home Inspector has only a limited amount of time to go through the property, the Inspection is not technically exhaustive.

Some conditions noted, such as foundation cracks or other signs of settling in a house, may either be cosmetic or may indicate a potential problem that is beyond the scope of the Home Inspection.

If you are concerned about any conditions noted in the Home Inspection Report, we strongly recommend that you consult a qualified Licensed Contractor or Consulting Engineer. These professionals can provide a more detailed analysis of any conditions noted in the Report at an additional cost

2) THE INSPECTION IS AN OPINION OF THE PRESENT CONDITION OF THE VISIBLE COMPONENTS.

The Home Inspector's Report is an opinion of the present condition of the property. It is based on a visual examination of the readily accessible features of the building.

A Home Inspection does not include identifying defects that are hidden behind walls, floors or ceilings. This includes wiring, heating, cooling, structure, plumbing and insulation that are hidden or inaccessible.

Some intermittent problems may not be obvious on a Home Inspection because they only happen under certain circumstances. As an example, your Home Inspector may not discover leaks that occur only during certain weather conditions or when a specific tap or appliance is being used in everyday life.

AGREEMENT

Report No. 3863

118 Torbrick Road, Toronto, ON September 8, 2023

Home Inspectors will not find conditions that may only be visible when storage or furniture is moved. They do not remove wall coverings (including wallpaper) or lift flooring (including carpet) or move storage to look underneath or behind.

3) THE INSPECTION DOES NOT INCLUDE HAZARDOUS MATERIALS.

This includes building materials that are now suspected of posing a risk to health such as phenol-formaldehyde and urea-formaldehyde based insulation, fiberglass insulation and vermiculite insulation. The Inspector does not identify asbestos roofing, siding, wall, ceiling or floor finishes, insulation or fireproofing. We do not look for lead or other toxic metals in such things as pipes, paint or window coverings.

The Inspection does not deal with environmental hazards such as the past use of insecticides, fungicides, herbicides or pesticides. The Home Inspector does not look for, or comment on, the past use of chemical termite treatments in or around the property.

4) WE DO NOT COMMENT ON THE QUALITY OF AIR IN A BUILDING.

The Inspector does not try to determine if there are irritants, pollutants, contaminants, or toxic materials in or around the building.

The Inspection does not include spores, fungus, mold or mildew that may be present. You should note that whenever there is water damage noted in the report, there is a possibility that mold or mildew may be present, unseen behind a wall, floor or ceiling.

If anyone in your home suffers from allergies or heightened sensitivity to quality of air, we strongly recommend that you consult a qualified Environmental Consultant who can test for toxic materials, mold and allergens at additional cost.

5) WE DON'T LOOK FOR BURIED TANKS.

Your Home Inspector does not look for and is not responsible for fuel oil, septic or gasoline tanks that may be buried on the property. If the building had its heating system converted from oil, there will always be the possibility that a tank may remain buried on the property.

If fuel oil or other storage tanks remain on the property, you may be responsible for their removal and the safe disposal of any contaminated soil. If you suspect there is a buried tank, we strongly recommend that you retain a qualified Environmental Consultant to determine whether this is a potential problem.

6) TIME TO INVESTIGATE

We will have no liability for any claim or complaint if conditions have been disturbed, altered, repaired, replaced or otherwise changed before we have had a reasonable period of time to investigate.

7) REPORT IS FOR OUR CLIENT ONLY

The inspection report is for the exclusive use of the client named herein. No use of the information by any other party is intended.

AGREEMENT

118 Torbrick Road, Toronto, ON September 8, 2023

8) CANCELLATION FEE

If the inspection is cancelled within 24 hours of the appointment time, a cancellation fee of 50% of the inspection fee will apply.

9) NOT A GUARANTEE, WARRANTY OR INSURANCE POLICY.

The inspection is not a guarantee, warranty or an insurance policy with regard to the fitness of the property.

10) LIMIT OF LIABILITY / LIQUIDATED DAMAGES

The liability of the Home Inspector and the Home Inspection Company arising out of this Inspection and Report, for any cause of action whatsoever, whether in contract or in negligence, is limited to a refund of the fees that you have been charged for this inspection.

I, Trevor Bond (Signature) _____, (Date) _____, have read, understood and accepted the terms of this agreement.

I, Listing Agent (Signature) _____, (Date) _____, have read, understood and accepted the terms of this agreement.

SUMMARY

118 Torbrick Road, Toronto, ON September 8, 2023

SUMMARY

ROOFING

EXTERIOR

STRUCTURE

ELECTRICAL

HEATING

COOLING

INSULATION

PLUMBING

INTERIOR

REFERENCE

1981 construction in good overall condition.

This Summary outlines potentially significant issues from a cost or safety standpoint. This section is provided as a courtesy and cannot be considered a substitute for reading the entire report. Please read the complete document.

[Priority Maintenance Items](#)

Heating

FURNACE \ Life expectancy

Condition: • [Near end of life expectancy](#)

Furnace is 17 years old, budget for replacement in next few years.

Implication(s): Equipment failure | No heat for building

Location: Basement

Task: Replace

Time: Unpredictable

Cost: \$4500

Cooling & Heat Pump

AIR CONDITIONING \ Life expectancy

Condition: • [Near end of life expectancy](#)

A/C is 17 years old, budget for replacement.

Implication(s): Equipment failure | Reduced comfort

Task: Replace

Time: Unpredictable

Cost: \$3500

This concludes the Summary section.

The remainder of the report describes each of the home's systems and also details any recommendations we have for improvements. Limitations that restricted our inspection are included as well.

The suggested time frames for completing recommendations are based on the limited information available during a pre-purchase home inspection. These may have to be adjusted based on the findings of specialists.

[Home Improvement - ballpark costs](#)

ROOFING

118 Torbrick Road, Toronto, ON September 8, 2023

SUMMARY

ROOFING

EXTERIOR

STRUCTURE

ELECTRICAL

HEATING

COOLING

INSULATION

PLUMBING

INTERIOR

REFERENCE

Description

The home is considered to face: • South

Sloped roofing material:

- [Asphalt shingles](#)



1.



2.

Probability of leakage: • Low

Approximate age: • 6 years

Limitations

Inspection performed: • By walking on roof

Recommendations

RECOMMENDATIONS \ Overview

1. **Condition:** • No roofing recommendations are offered as a result of this inspection. Roof in good condition.

EXTERIOR

118 Torbrick Road, Toronto, ON September 8, 2023

SUMMARY

ROOFING

EXTERIOR

STRUCTURE

ELECTRICAL

HEATING

COOLING

INSULATION

PLUMBING

INTERIOR

REFERENCE

Description

Gutter & downspout material: • [Aluminum](#)

Downspout discharge: • [Above grade](#)

Lot slope: • [Flat](#)

Soffit (underside of eaves) and fascia (front edge of eaves): • [Aluminum](#)

Wall surfaces and trim: • [Metal siding](#) • [Brick](#)

Driveway: • Interlocking brick

Walkway: • Pavers • Stone

Deck: • Ground level • Pressure-treated wood

Exterior steps: • Concrete

Patio: • Pavers

Limitations

No or limited access to: • Area below steps, deck, porches

Recommendations

ROOF DRAINAGE \ Gutters

2. Condition: • [Clogged](#)

Implication(s): Chance of water damage to structure, finishes and contents

Location: Exterior

Task: Clean

Time: Regular maintenance

Cost: Minor

WALLS \ Masonry (brick, stone) and concrete

3. Condition: • [Spalling](#)

Minor masonry repair needed at first floor window sill.


Implication(s): Weakened structure | Chance of structural movement

Location: South Exterior

Task: Repair or replace

Time: Unpredictable

Cost: Minor



3.

STRUCTURE

Report No. 3863

118 Torbrick Road, Toronto, ON September 8, 2023

SUMMARY

ROOFING

EXTERIOR

STRUCTURE

ELECTRICAL

HEATING

COOLING

INSULATION

PLUMBING

INTERIOR

REFERENCE

Description

Configuration: • [Basement](#) • [Crawlspace](#)
Foundation material: • [Poured concrete](#) • [Masonry block](#)
Floor construction: • [Joists](#) • Subfloor - OSB (Oriented Strand Board)
Exterior wall construction: • [Wood frame / Brick veneer](#)
Roof and ceiling framing: • Rafters • [Plywood sheathing](#)
Party wall: • [Masonry](#)

Limitations

Inspection limited/prevented by: • Storage
Attic/roof space:
• Inspected from access hatch
South hatch only, very limited access.
• No access
North hatch painted shut.
Percent of foundation not visible: • 50 %

Recommendations

FOUNDATIONS \ General notes

4. Condition: • Typical minor cracks
Typical minor cracks are not structurally significant. Cracks are at party wall and therefore not vulnerable to leakage.



4.

Description

Service entrance cable and location: • [Underground - cable material not visible](#)

Service size: • [100 Amps \(240 Volts\)](#)

Main disconnect/service box rating: • [100 Amps](#)

Main disconnect/service box type and location: • [Breakers - first floor](#)

System grounding material and type: • [Not visible](#)

Distribution panel type and location: • [Breakers - basement](#)

Distribution panel rating: • [100 Amps](#)

Auxiliary panel (subpanel) type and location: • [Breakers - basement](#)

Distribution wire (conductor) material and type: • [Copper - non-metallic sheathed](#)

Type and number of outlets (receptacles): • [Grounded - typical](#)

Circuit interrupters: Ground Fault (GFCI) & Arc Fault (AFCI): • No AFCI • Gfci's in some areas only.

Limitations

Not included as part of a building inspection: • Concealed Wiring

Recommendations

DISTRIBUTION SYSTEM \ Wiring (wires) - installation

5. Condition: • Cover exposed wiring with conduit.

Location: Exterior

Task: Protect

Time: Immediate

Cost: Minor



5.

DISTRIBUTION SYSTEM \ Outlets (receptacles)

6. Condition: • [GFCI/GFI needed \(Ground Fault Circuit Interrupter\)](#)


Implication(s): Electric shock

Location: Exterior

Task: Replace

Time: Immediate

Cost: Minor



6.

DISTRIBUTION SYSTEM \ Cover plates

7. Condition: • [Missing](#)


Implication(s): Electric shock

Location: Basement and shed

Task: Provide

Time: Immediate

Cost: Minor



7.

DISTRIBUTION SYSTEM \ Smoke alarms (detectors)

8. Condition: • Missing

Ensure each floor has operable smoke/carbon monoxide detectors.

Implication(s): Safety issue

Location: Various

Task: Provide

Time: Immediate

Cost: Minor



8.

HEATING

118 Torbrick Road, Toronto, ON September 8, 2023

- SUMMARY
 - ROOFING
 - EXTERIOR
 - STRUCTURE
 - ELECTRICAL
 - HEATING**
 - COOLING
 - INSULATION
 - PLUMBING
 - INTERIOR
- REFERENCE

Description

Heating system type: • [Furnace](#)
Fuel/energy source: • [Gas](#)
Heat distribution: • [Ducts and registers](#)
Approximate capacity: • [65,000 BTU/hr](#)
Efficiency: • [Mid-efficiency](#)
Approximate age: • [17 years](#)
Main fuel shut off at: • Meter
Failure probability: • [High](#)
Air filter: • Disposable
Chimney/vent: • [Metal](#)
Humidifier: • None

Limitations

Warm weather: • Prevents testing heating effectiveness
Heat loss calculations: • Not done as part of a building inspection

Recommendations

FURNACE \ Life expectancy
9. Condition: • [Near end of life expectancy](#)
Furnace is 17 years old, budget for replacement in next few years.
Implication(s): Equipment failure | No heat for building
Location: Basement
Task: Replace
Time: Unpredictable
Cost: \$4500

COOLING & HEAT PUMP

118 Torbrick Road, Toronto, ON September 8, 2023

- SUMMARY
 - ROOFING
 - EXTERIOR
 - STRUCTURE
 - ELECTRICAL
 - HEATING
 - COOLING**
 - INSULATION
 - PLUMBING
 - INTERIOR
- REFERENCE

Description

Air conditioning type: • [Air cooled](#) • Central
Cooling capacity: • [24,000 BTU/hr](#)
Compressor approximate age: • 17 years
Failure probability: • [High](#)

Limitations

Heat gain calculations: • Not done as part of a building inspection

Recommendations

AIR CONDITIONING \ Life expectancy
10. Condition: • [Near end of life expectancy](#)
A/C is 17 years old, budget for replacement.
Implication(s): Equipment failure | Reduced comfort
Task: Replace
Time: Unpredictable
Cost: \$3500

Description

Attic/roof insulation material: • [Glass fiber](#)

Attic/roof insulation amount/value: • [R-32](#)

Attic/roof air/vapor barrier: • Not determined

Attic/roof ventilation: • [Roof and soffit vents](#)

Wall insulation material: • [Glass fiber](#)

Wall insulation amount/value: • [R-12](#) • Spot checked only

Wall air/vapor barrier: • Kraft paper

Foundation wall insulation material: • [Glass fiber](#) • [Plastic/foam board](#)

Foundation wall insulation amount/value: • 0-12

Limitations

Inspection limited/prevented by lack of access to:

- Attic

Limited access to south attic, north attic hatch sealed and not accessed.

Recommendations

RECOMMENDATIONS \ Overview

11. **Condition:** • Increased insulation is an improvement and not an essential repair.

FOUNDATION \ Interior insulation

12. **Condition:** • [Exposed combustible insulation](#)

Remove styrofoam or cover with drywall.

Implication(s): Fire hazard

Location: North Basement

Task: Protect

Time: Immediate

Cost: Minor

INSULATION AND VENTILATION

Report No. 3863

118 Torbrick Road, Toronto, ON September 8, 2023

SUMMARY

ROOFING

EXTERIOR

STRUCTURE

ELECTRICAL

HEATING

COOLING

INSULATION

PLUMBING

INTERIOR

REFERENCE



9.

Description

Water supply source (based on observed evidence): • Public

Service piping into building: • Polybutylene

Supply piping in building: • [Copper](#) • PEX (cross-linked Polyethylene)

Main water shut off valve at the: • Furnace room

Water flow and pressure: • Good

Water heater type: • [Conventional](#) • Tank • Rental

Water heater fuel/energy source: • [Gas](#)

Water heater tank capacity: • 151 liters

Water heater approximate age: • 12 years

Water heater failure probability: • [Low](#)

Waste and vent piping in building: • [ABS plastic](#)

Pumps: • None

Floor drain location: • Near water heater

Backwater valve: • Not present

Limitations

Items excluded from a building inspection: • Concealed plumbing

Recommendations

FIXTURES AND FAUCETS \ Shower stall

13. Condition: • [Pooling water on the floor](#)

Replace threshold strip at base of shower door.

Implication(s): Chance of water damage to structure, finishes and contents

Location: Third Floor Ensuite Bathroom

Task: Improve

Time: Before use

Cost: Minor



10.

Description

Major floor finishes: • [Concrete](#) • Engineered wood

Major wall finishes: • [Plaster/drywall](#)

Major ceiling finishes: • [Plaster/drywall](#)

Windows: • [Fixed](#) • [Sliders](#) • [Casement](#) • [Awning](#)

Glazing: • [Double](#)

Exterior doors - type/material: • Hinged • [Sliding glass](#) • Metal-clad

Party wall: • [Masonry](#)

Limitations

Inspection limited/prevented by: • Storage/furnishings

Not included as part of a building inspection: • Appliances

Percent of foundation not visible: • 50 %

Recommendations

WINDOWS \ Hardware

14. Condition: • [Broken](#)

Implication(s): System inoperative or difficult to operate

Location: North Second Floor Bedroom

Task: Replace

Time: Before use

Cost: Minor



11.

BASEMENT \ Wet basement - evidence


15. Condition: • [Efflorescence](#)

Typical minor efflorescence. Install interior membrane before insulating crawlspace.

Implication(s): Chance of water damage to structure, finishes and contents

Location: South Crawl Space

Task: Monitor



12.



13.

END OF REPORT

The links below connect you to a series of documents that will help you understand your home and how it works. These are in addition to links attached to specific items in the report.

Click on any link to read about that system.

» 01. ROOFING, FLASHINGS AND CHIMNEYS

» 02. EXTERIOR

» 03. STRUCTURE

» 04. ELECTRICAL

» 05. HEATING

» 06. COOLING/HEAT PUMPS

» 07. INSULATION

» 08. PLUMBING

» 09. INTERIOR

» 10. APPLIANCES

» 11. LIFE CYCLES AND COSTS

» 12. SUPPLEMENTARY

Asbestos

Radon

Urea Formaldehyde Foam Insulation (UFFI)

Lead

Carbon Monoxide

Mold

Household Pests

Termites and Carpenter Ants

» 13. HOME SET-UP AND MAINTENANCE

» 14. MORE ABOUT HOME INSPECTIONS