

"Canadian owned, Satisfying customers since 1968"

1828 Danforth Avenue Toronto, Ontario M4C 1H8 Tel: 416-469-4111

> Fax: 416- 469-3791 www.aetnapest.ca

Name: Trevor Bond
Address of property inspected: 54 Month new Due
Torondo, and M4K 2A1
Termite Inspection Report
Comments: Evidence of mactive termite sheller tubes found in
the Sollowing location
- around the poured column holding up rear deck near
Soundation to yords staircase
on 2"x4" beside downsport north west corner.
- in interior of garage in 2"x4" soull west corner new
Lop plade
in interior of garage on concrete curb north and east side.
The above properly was treated in 1997 but currently
no dernide descondy.
COST\$ 270.00
HST \$35.10
TOTALA 305.10
This inspection is limited to those parts of the structure(s) that are visible and accessible at the time of the inspection.

The inspection covers only the multi-family structure, primary dwelling, or place of business. Sheds, detached garages, lean-tos, fences, guest houses and/or any other structure will not be included in this inspection report unless specifically noted in the report.

and stored articles and (2) any portion of the structure in which inspection would necessitate removing or defacing any part of the structure(s) (including the surface appearance of the structure). The inspection does not cover any condition or damage which was not visible in or on the structure(s) at the time of inspection but which may be

Inspectors from Aetna Pest Control are not engineers or qualified builders. It is always recommended to get a qualified expert where structural damage is a concern.

Thank you for contacting Aetna Pest Control Ltd., and if you require any further information please telephone us at 416-469-4111.

revealed in the course of repair or replacement work.

Inspection Performed by:

HST #R100068832

Travis McAleur Date: Oct 9, 20

(Signature)

Name (Print)